RCRA RECORDS CENTER
FACILITY POAR Whitney - Main St.
I.D. NO. CTD 990672081
FILE LOC. R-1B
OTHER RDMS #2715

UNITED
TECHNOLOGIES
Pratt & Whitney

AUG 3 I

REGIC OFFICE (

4080 M. 1

400 Main Street East Hartford, CT 060108 Environmental Compliance

August 21, 1989

U. S. Environmental Protection Agency JFK Federal Building Boston, MA 02203 ATTN: Mr. Michael Deland

Connecticut Department of Environmental Protection 165 Capitol Avenue Hartford, CT 06106 ATTN: Ms. Leslie Carothers

Dear Mr. Deland and Ms. Carothers:

This letter is intended to fulfill our obligation under 40 CFR 265.56(j) and 22a-449(C)(26)(f)(10) of the Code of Federal Regulations and the Regulations of the State of Connecticut, respectively, to report on any incident requiring the activation of our Contingency Plan.

Owner:

United Technologies Corporation One Financial Center Hartford, CT 06101 (203) 728-7000

Facility:

Pratt & Whitney 400 Main Street East Hartford, CT 06108 (203) 565-3833

Location: H Building - Col. Q-10

Date of spill/incident:8/9/89 Time: 1400 Hrs

Material involved: Acid Mixture - Gaseous Quantity: Gaseous

Description or cause of spill/incident: A mixture of acid was being prepared by D-1017 personnel and the scrubber could not accommodate the concentration of the chemicals. The result was a release of the fumes through the roof vent on H-building, the wind carried the fumes south across H-Building. The air conditioning units south of the area pulled in the fumes and forced the evacuation of the offices in H-Building.

Extent of contamination and injuries: The offices in H-Building were evacuated and there were no injuries.

Corrective action taken: The process for the mixing of acids was reviewed and it was determined that more time would be taken between the mixing of the different chemicals, this would result in a less violent reaction.

Richard E. Atwood

Supervisor, Environmental Compliance

REA/JJK/jjk